Change Modes

## Change from Mode2 to grandMA3 on Consoles

To change from Mode2 to grandMA3:

1. Restart the console by using the **Restart Keyword**. A pop-up opens:

Restart pop-up

3. Confirm the pop-up. The Mode2 application closes and the console restarts.
4. The Mode Selection pop-up appears. Tap 3 .

Mode Selection Dialog

SwitchTograndMA3Software Keyword

Requirements: A grandMA3 station running in Mode2.

- To switch from Mode2 to grandMA3, use the **SwitchTograndMA3Software** keyword described in the grandMA3 User Manual.

Reboot Processing Unit from Mode2 to grandMA3

To change the application for the processing unit:

1. Tap `Reboot` on the left side of the processing unit main screen. A pop-up opens.

Processing Unit

2. Tap `Yes`. The processing unit reboots.

Pop-up

3. Continue as described in **Change from Mode2 to grandMA3 on Consoles**.

xPort Node from Mode2 to grandMA3

- To change the xPort Node from Mode2 to grandMA3, follow these instructions:

Mode2 screen:

- To switch to grandMA3, press and hold the rotary knob. The display cycles through the following screens:

- Release the rotary knob at the following screen:

- Press the rotary knob to confirm.

The xPort Node reboots into grandMA3 mode.

For more information about changing from grandMA3 mode to Mode2, read the topic **Control other MA devices** in the **grandMA3 User Manual**.