

Update grandMA3 onPC Windows Hardware

Updating the grandMA3 onPC software for the grandMA3 onPC windows hardware, such as grandMA3 onPC command wing XT or grandMA3 onPC rack-unit, is similar to the update process for grandMA3 onPC windows.

For more information on how to update a grandMA3 on PC for windows, see the Windows installation topic.

Important: Select the grandMA3 onPC installer for Windows from the download section!

Reset to Factory Defaults

Use the following instruction to fully clean the drive or to remove your files from the drive.

Install the complete windows recovery installation package on the hard drive. This includes the operating system and the grandMA3 onPC software information.

The windows recovery installation package always installs the latest version of the grandMA3 onPC software and the Windows updates!

To download the windows recovery installation package:

- 1. Go to the download area of grandMA3.
- 2. Click on grandMA3 onPC Windows Hardware Image x.x.x.x . The EULA and Third-Party Acknowledgements popup opens.
- 3. Click Accept and download . A pop-up opens.
- 4. Enter the serial number and pin as descibed in the pop-up:



vnload".	yyyyyy and Pin cou	e P 2222 into the boxes	below and then click Start
Serial Number			
XXXXXXXXXX		- уууууу	
Pin			
Pzzzz			
Start Download			Deny

Pop-up in the download area

5. Click Start Download to download the file.

To install the windows recovery installation package:

- 1. Extract the entire data from the zip file and copy it onto a USB flash drive (FAT32 formatted, minimum 8 GB).
- 2. Insert the USB flash drive.
- 3. Power up the grandMA3 onPC command wing XT or grandMA3 onPC rack-unit.
- 4. If necessary, tap F8 to choose Boot device and select boot from USB.
- 5. Choose a keyboard layout, for example, US.





6. Click Recover from a drive





. Hint:

> If the "Recover from a drive" option does not appear, the USB flash drive may be faulty. Try another USB flash drive and make sure that the files are properly unzipped.

7. Click Just remove my files . If you want to do a complete clean install without keeping any user files, continue with Fully clean the drive .





8. Click Recover . The License Agreement opens.



9. Click Accept . The system restarts several times.



Account	
Windows 10 License Agreement	
	st updated June 2018
IF YOU LIVE IN (OR IF YOUR PRINCIPAL PLACE OF BUSINESS IS IN) THE UNITED STATES, PLEASE READ THE BINDIN CLAUSE AND CLASS ACTION WAIVER IN SECTION 11. IT AFFECTS HOW DISPUTES ARE RESOLVED.	G ARBITRATION
Thank you for choosing Microsoft!	
Depending on how you obtained the Windows software, this is a license agreement between (i) you and the devic software installer that distributes the software with your device; or (ii) you and Microsoft Corporation (or, based or if a business, where your principal place of business is located, one of its affiliates) if you acquired the software fro Microsoft is the device manufacturer for devices produced by Microsoft or one of its affiliates, and Microsoft is the acquired the software directly from Microsoft. Note that if you are a volume license customer, use of this software volume license agreement rather than this agreement.	e manufacturer or h where you live or, m a retailer. e retailer if you is subject to your
This agreement describes your rights and the conditions upon which you may use the Windows software. You should revie	w the entire
	Accept
Ф	





10. The MA Shell Launcher starts for the first time.







Configure the Settings

1. To configure the touch screens, click Touch Settings



2. To set the desired screen configuration, click Display Settings

grandMA3 onPC command wing XT	Settings Moree Find a setting System	- C × Display Rearrange your displays Select a display below to change the settings for it. Press and hold (or select) a display, then drag to rearrange a.
Control of the second s	Display	4 3 2 1
	Sounge Sublet mode Multitusking Projecting to this PC X Shared experiences	Identify Detect Color Night light Corr
Tools: Tools: Deploy settings Network settings Open windows: Serrya Stadown Stadown) Equiner Windows 10 Settinga)	Windows Budde Golds Windows

2. To set the desired screen configuration, click Display Settings .

© 2025 MA Lighting Technology GmbH - Dachdeckerstr. 16 - 97297 Waldbüttelbrunn - Germany Phone +49 5251 688865-30 - support@malighting.com - www.malighting.com



grandMA3 on PC command wing XT	Notwork Connections Organice Disable this network device Cent Disable this network device Cent Disable this network Readed PCIe Did Family Content	Behverk and Internet > Network Connections v b Sn e Dagress this connection Rename this connection View status of this connection e Signerified instruction Rename this connection View status of this connection e Signerified instruction Rename this connection View status of this connection e Signerified instruction Rename this connection View status of this connection	- C × auch Naturals Connection P Change settings of this connection P • • • •	
garantino 3 and 1 2 8 2 Terminol	Const Status General Davestion Prv4-Convectivity: Drv4 Convectivity: Media States Davators:	a Q Cent Properties X Meteolog (partig) Correct using		
(C) (period (C) 12.82	Speed Detable Atbdy	Patha KCs GE Factor Contexts # Internet Protection Variant 4 (CP/Public Properties × Internet Protection Variant 4 (CP/Public Properties × Contexts # Contexts# Contexts # Contexts # Contexts # Contexts # C	D1 90	
Tools: Tools Deple utilings Natesk utilings Open windows; United -free Con13a.a Shabes Shabes Con13a.a	Explorer Windows 10 5	Administ (Kd surver:		



Hint:

If an incorrect motherboard is installed or if the windows recovery installer package is installed on a different device, you receive the following error message.

In X:\windows\system32\cmd.exe - startnet.cmd	
Error: grandMA3 onPC OEM hardware not detected! Press any key to shutdown system. No changes have been made to your system.	Â
Press any key to continue	
	~